


US EPA ARCHIVE DOCUMENT

<b>1. Incident Name</b>	<b>2. Date Prepared</b>	<b>3. Time Prepared</b>	<b>UNIT LOG ICS 214</b>			
Kalamazoo River/Enbridge Spill	05/09/2012	1600				
<b>4. Unit Name/Designators</b>	<b>5. Unit Leader</b>		<b>6. Operational Period :</b>			
SOTF Team #5	<b>Name:</b>	Dan Capone & Joe Victory (START/US EPA)	<b>From:</b>	05/03/2012 0700		
	<b>Position:</b>	Operations Section Chief	<b>To:</b>	05/10/2012 0700		
<b>7. Personnel Roster Assigned</b>						
<u><b>Name</b></u>	<u><b>ICS Position</b></u>	<b>LL</b>				
Dan Capone	Operations Section Chief					
Joe Victory	Operations Section Chief					
Dan Zahner	Field Team Lead					
Brennan Pierce	SOTF5					
<b>8. Activity Log</b>						
<b>Activity Area</b>	<b>Morrow Lake Delta</b>	<b>LAT</b>	<b>LAT</b>			
		<b>Various</b> (DD.MMMM)	<b>Various</b> (DD.MMMM)			
<b><u>OIL OBSERVED</u></b>	<b>EXTENT OF OIL IMPACTED AREA</b>	NA				
	<b>DENSITY OF OIL /SHEEN</b>	NA				
<b>Total Collection Points</b>	NA					
<b>Total Boom Deployed</b>	NA					
<b>Activity</b>	<b><u>START SOTF Team 5 Activity:</u></b>					
	SOTF 5 team members Brennan Pierce and Cory Graves of Tetra Tech attempted to begin poling operations in the Morrow Lake delta. After taking several temperature readings, it was determined that the delta sediment did not reach the required 60°F necessary to begin poling. Instead, the team numbered and flagged the islands of the delta in cooperation with SOTF 6 in anticipation of future poling operations, while periodically monitoring sediment temperature conditions. Delta SOTF operations were called off at approximately 1400 when it was determined that poling could not be completed for the remainder of the day.					
	<b>LOC. ID</b>	<b>Water Depth (ft)</b>	<b>Soft Push (ft)</b>	<b>Hard Push (ft)</b>	<b>Sediment / Above Sed / Surface / Air (°F)</b>	<b>Sediment Type/ and Sheen Observation</b>

[illegible]